

















COMBO BUILD™






Did you install 2 AA (or LR6) batteries in the motor?















Flip model upside down









Flip model right side up

