










# Swing Ride





Did you install 2 AA (or LR6) batteries in the motor?





















































# Swing Ride



1 - 18



1 - 17

18